



Center for Family Services Headstart  
100 Maplegrove Boulevard  
Lumberton, NJ 08048

7/18/2024 14:17  
SAMPLE NUMBER: X4383  
DATE SAMPLED: 7/5/24  
DATE/TIME RECEIVED: 7/5/24 12:53  
COLLECTED BY: Client

## CERTIFICATE OF ANALYSIS

N.J.D.E.P. CERTIFICATION # 06003

Results in mg/(ppm) unless otherwise noted

Sample #	Sample Location	Date Sampled	Sample Time	DF	RL	Copper	Date Analyzed
X4383-1	Kitchen HW #1	7/5/2024	7:11	1	0.050	0.173	7/11/24 11:20
X4383-2	Kitchen Utility Sink #1	7/5/2024	7:12	1	0.050	0.117	7/11/24 11:21
X4383-3	Kitchen Utility Sink #2	7/5/2024	7:14	1	0.050	0.105	7/11/24 11:21
X4383-4	Water Fountain	7/5/2024	7:16	1	0.050	<0.05	7/11/24 11:22
X4383-5	Kitchen Utility Sink #3	7/5/2024	7:18	1	0.050	<0.05	7/11/24 11:22
X4383-6	Class #2	7/5/2024	7:21	1	0.050	0.086	7/11/24 11:23
X4383-7	Class #2 Bathroom	7/5/2024	7:22	1	0.050	0.082	7/11/24 11:24
X4383-8	Class #1	7/5/2024	7:24	1	0.050	0.328	7/11/24 11:27
X4383-9	Class #1 Bathroom	7/5/2024	7:26	1	0.050	0.176	7/11/24 11:28
X4383-10	Class #7	7/5/2024	7:28	1	0.050	<0.05	7/11/24 11:28
X4383-11	Class #7 Bathroom	7/5/2024	7:30	1	0.050	0.054	7/11/24 11:29
X4383-12	Class #8	7/5/2024	7:31	1	0.050	<0.05	7/11/24 11:29
X4383-13	Class #8 Bathroom	7/5/2024	7:32	1	0.050	0.051	7/11/24 11:30
X4383-14	Class #3	7/5/2024	7:34	1	0.050	0.125	7/11/24 11:31
X4383-15	Class #3 Bathroom	7/5/2024	7:36	1	0.050	0.15	7/11/24 11:31
X4383-16	Class #4	7/5/2024	7:38	1	0.050	0.131	7/11/24 11:32
X4383-17	Class #4 Bathroom	7/5/2024	7:39	1	0.050	0.077	7/11/24 11:32
X4383-18	Water Fountain #1	7/5/2024	7:42	1	0.050	0.33	7/11/24 11:36
X4383-19	Water Fountain #2	7/5/2024	7:43	1	0.050	0.351	7/11/24 11:36
X4383-20	Mens Room Right Sink	7/5/2024	7:45	1	0.050	0.055	7/11/24 11:37
X4383-21	Mens Room Left Sink	7/5/2024	7:47	1	0.050	0.118	7/11/24 11:38
X4383-22	Ladies Room Right Sink	7/5/2024	7:49	1	0.050	<0.05	7/11/24 11:38
X4383-23	Ladies Room Left Sink	7/5/2024	7:50	1	0.050	0.068	7/11/24 11:39
X4383-24	Water Fountain #3	7/5/2024	7:59	1	0.050	0.362	7/11/24 11:39
X4383-25	Water Fountain #4	7/5/2024	8:00	1	0.050	0.357	7/11/24 11:40
X4383-26	Class #9	7/5/2024	8:02	1	0.050	0.065	7/11/24 11:42
X4383-27	Class #9 Bathroom	7/5/2024	8:03	1	0.050	<0.05	7/11/24 11:43
X4383-28	Class #10	7/5/2024	8:05	1	0.050	0.193	7/11/24 11:45
X4383-29	Class #10 Bathroom	7/5/2024	8:06	1	0.050	0.242	7/11/24 11:45
X4383-30	Class #5	7/5/2024	8:08	1	0.050	0.071	7/11/24 11:40
X4383-31	Class #5 Bathroom	7/5/2024	8:10	1	0.050	<0.05	7/11/24 11:46
X4383-32	Class #6	7/5/2024	8:12	1	0.050	<0.05	7/11/24 11:47
X4383-33	Class #6 Bathroom	7/5/2024	8:13	1	0.050	<0.05	7/11/24 11:48

Lalish Menghani  
Lab Director



Center for Family Services Headstart  
100 Maplegrove Boulevard  
Lumberton, NJ 08048

7/18/2024 14:02  
SAMPLE NUMBER: X4383  
DATE SAMPLED: 7/5/24  
DATE/TIME RECEIVED: 7/5/24 12:53  
COLLECTED BY: Client

### CERTIFICATE OF ANALYSIS

N.J.D.E.P. CERTIFICATION # 06003

Results in mg/l(ppm) unless otherwise noted

Sample #	Sample Location	Date Sampled	Sample Time	DF	RL	Lead	Date Analyzed
X4383-1	Kitchen HW #1	7/5/2024	7:11	1	0.002	0.00275	7/9/24 12:15
X4383-2	Kitchen Utility Sink #1	7/5/2024	7:12	1	0.002	<0.002	7/9/24 12:20
X4383-3	Kitchen Utility Sink #2	7/5/2024	7:14	1	0.002	<0.002	7/9/24 12:25
X4383-4	Water Fountain	7/5/2024	7:16	1	0.002	<0.002	7/9/24 12:30
X4383-5	Kitchen Utility Sink #3	7/5/2024	7:18	1	0.002	<0.002	7/9/24 12:35
X4383-6	Class #2	7/5/2024	7:21	1	0.002	<0.002	7/9/24 13:00
X4383-7	Class #2 Bathroom	7/5/2024	7:22	1	0.002	<0.002	7/9/24 13:05
X4383-8	Class #1	7/5/2024	7:24	1	0.002	<0.002	7/9/24 13:10
X4383-9	Class #1 Bathroom	7/5/2024	7:26	1	0.002	<0.002	7/9/24 13:15
X4383-10	Class #7	7/5/2024	7:28	1	0.002	<0.002	7/9/24 13:20
X4383-11	Class #7 Bathroom	7/5/2024	7:30	1	0.002	<0.002	7/9/24 13:25
X4383-12	Class #8	7/5/2024	7:31	1	0.002	<0.002	7/9/24 13:30
X4383-13	Class #8 Bathroom	7/5/2024	7:32	1	0.002	<0.002	7/9/24 13:35
X4383-14	Class #3	7/5/2024	7:34	1	0.002	0.0033	7/9/24 13:40
X4383-15	Class #3 Bathroom	7/5/2024	7:36	1	0.002	0.00592	7/9/24 13:55
X4383-16	Class #4	7/5/2024	7:38	1	0.002	<0.002	7/10/24 13:05
X4383-17	Class #4 Bathroom	7/5/2024	7:39	1	0.002	<0.002	7/10/24 13:10
X4383-18	Water Fountain #1	7/5/2024	7:42	1	0.002	<0.002	7/10/24 13:15
X4383-19	Water Fountain #2	7/5/2024	7:43	1	0.002	<0.002	7/10/24 13:20
X4383-20	Mens Room Right Sink	7/5/2024	7:45	1	0.002	<0.002	7/10/24 13:35
X4383-21	Mens Room Left Sink	7/5/2024	7:47	1	0.002	<0.002	7/10/24 13:50
X4383-22	Ladies Room Right Sink	7/5/2024	7:49	1	0.002	<0.002	7/10/24 13:55
X4383-23	Ladies Room Left Sink	7/5/2024	7:50	1	0.002	<0.002	7/10/24 14:00
X4383-24	Water Fountain #3	7/5/2024	7:59	1	0.002	<0.002	7/10/24 14:05
X4383-25	Water Fountain #4	7/5/2024	8:00	1	0.002	<0.002	7/10/24 14:10
X4383-26	Class #9	7/5/2024	8:02	1	0.002	<0.002	7/10/24 14:15
X4383-27	Class #9 Bathroom	7/5/2024	8:03	1	0.002	<0.002	7/10/24 14:30
X4383-28	Class #10	7/5/2024	8:05	1	0.002	<0.002	7/10/24 14:35
X4383-29	Class #10 Bathroom	7/5/2024	8:06	1	0.002	<0.002	7/10/24 14:40
X4383-30	Class #5	7/5/2024	8:08	1	0.002	<0.002	7/10/24 14:45
X4383-31	Class #5 Bathroom	7/5/2024	8:10	1	0.002	0.00325	7/10/24 15:05
X4383-32	Class #6	7/5/2024	8:12	1	0.002	<0.002	7/10/24 15:10
X4383-33	Class #6 Bathroom	7/5/2024	8:13	1	0.002	<0.002	7/10/24 15:15

Lalish Menghani  
Lab Director